

14101 Old Gentilly Road
New Orleans, LA 70129
(504) 254-3600

1110 Howard Drive
Deer Park, TX 77536
(713) 479-5295

1660 South Beltline Hwy.
Mobile, AL 36609
(205) 666-3500

209 Factory Street
Jackson, MS 39202
(601) 948-2123



PETERSON-RIEDEL SERVICES

February 23, 1990

U.S. Environmental Protection Agency
1445 Ross Ave, Suite 1200
Dallas, Texas 75202-2733
Attn: Gary W. Guerra

Re: Laboratory analysis on four soil samples from the Grant Rd.
ERCS project

Dear Mr. Guerra;

Enclosed are the lab analysis for four soil samples taken on the Grant Road project. These four samples were taken after one drum (drum #30) of soil was excavated from areas where product was spilled during the overpacking phase. Analysis for the soil in drum #30 (mailed to you earlier) shows 7.7% liquid organics. This is to be expected since there was product spilled in this area. Here is a short summary of the four soil samples:

- S1 - No volatiles found, trace amounts of phthalate found, high metals found
- S2 - No volatiles found, trace amounts of esters found, high metals found
- S3 - Trace amounts of volatiles found, high metals found
- S4 - No volatiles found, trace amounts of phthalate found, high metals found

If you require any further information or have any questions please call me at 713-479-5295.

Sincerely,

Roe Sharma
Environmental Chemist
Riedel-Peterson Environmental Services

Enc

9024396

